Regarding Quality Control Certificate

Name of Work: Improvements to Roads and Drains at Dynasty Layout in Ward No. 6 Dasarahalli Village

Job No: 006-14-000040

Work Order No: 399/21-02-2014

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT & H at this stage is not feasible since this work was executed one ------ Year back.

Executive Engineer
Byatarayanapura Division
Bruhat Bangalore Mahanagara Palike